

CHASSIS BREAKDOWN DRAWINGS



POWER SUPPLY INSTALLATION



1) Remove the right side panel, then put into the PSU according to the arrowhead direction.

MOTHERBOARD INSTALLATION



Pre-installed 6 motherboard screws in facctory setting



2) Fix the screws



Put the motherboard into the right position according to the arrowhead direction, the fix the screws

Right side

Тор

Rear

(Picture 2)

2) loose the drop-proof screws A, hold the hand-holding position then pull out the side panel to the angle as picture two then pull up the side panel as the arrowhead direction.

HDD AND SSD INSTALLATION

HDD installation



Remove the front pane , hold the front panel like the pictures then pull out the front panel.

SSD installation







B. Assembly the SSD, fix the screws.



Fix the HDD into the HDD tool-less bracket accoding to the step \odot/\oslash then put inside the HDD bracket into the HHD slots obey to the arrowhead direction



C. Install the SSD into the chassis which is D. Fix the screws, installation finish near to top and left edge of the M/B bracket, put it into the right position then fixing.

- 06 -

0

GLASS SIDE PANEL INSTALLATION

1) Find the bolt on the glass panel

2) Aligning the bolt into the hole then insert into



3) Then install well the glass panel as picture, fix the screw

DISASSEMBLY FOR DUST -PROOF FILTER



VGA CARD HOLDER INSTALLATION





A. VGA Card Holder

motherboard plate according to the VGA

- 07 -

Installation



und head screws

the bottom side

Install and fix the Fix the bracket from

with a sleeve

PSU screws

VGA card

Fix the iron column to the bracket Fix the PCIE 16X cable on the VGA bracket



point direction





- 09 -

